

PressCAL High Accuracy Digital (Differential/Guage/Absolute) Pressure Indicator

TDP-01B Instrument Manual



TABLE OF CONTENTS

1. Preface	.3
2.Technical Specification	. 4
3. Understand the Instruments	5
3. Calibration	. 9
4. Warranty Certificate	.14

PREFACE

Welcome & thanks for purchasing Our PressCAL Model No-TDP-01B, Our high Accuracy pressure measurement instrument.

Please refer Technical specifications & instructions carefully before using the product.

STANDARED ACCESSORIES

Please check for following Standard accessories/Observation

- 1) Product is not physically damaged.
- 2) Operating manual With Warranty certificate
- 3) Silicon pressure tubes
- 5) Carrying Bag.

TECHNICAL SPECIFICATION

- 1. Measurement Range: Various models & ranges available ranging from 0-0.15 PSI & upto 100 PSI (Bidirection Pressure ranges also available in request).
- 2. Measurement Modes: Differential & Gauge pressure modes / Absolute pressure modes (Prior order basis).
- 3. High Accuracy: 0.1% Full scale
- 4. Resolution high resolution of 5 digits (For higher ranges depends upon the pressure range)
- 5. Linearity: Maximum 0.05% FS (Defined as best fit straight line)
- 6. User selectable 12 multiple Pressure measurement units: Kpa, pa, hPa,Bar,mBar, Kg/cm2, PSI, mmWC, inWC, cmWC, mmHG, cmHG.
- 7. Power supply: 2 AA dry batteries, user replaceable
- 8. Battery Back up: 2 Hrs Continuous use with back light on
- 9. Measurement Media: Clean Dry gas/Air only
- 10. Weight; 410 g without carry case
- 11. Enclosure Dimensions: 165 mm(L),100mm(B),35 mm(W)
- 12. Pressure push fit Nipples: 2 units

UNDERSTAND YOUR INSTRUMENT

- 1. Hi Pressure input (connect tube)
- 2. Low pressure Input (connect tube)
- 3. Instrument Switch ON /OFF button
- 4. Unit selection key (works as shift digit key in program mode)
- 5. Up Arrow key / Increment key (works as resetting key for resetting minimum & maximum values)
- 6. Zero Key/Enter (Press for 1 second to zero /tare the pressure display), this key works as "Enter" command in program mode
- 7. Light Key (switch On/Off for display light), keep display light off for better battery life
- 8. Battery level indicator
- 9. Unit display
- 10. Minimum & Maximum pressure display
- 11. Silicon protective cover (removable)



Battery compartment, Remove Silicon protective cover to replace the battery

Batteries: AA size alkaline



SWITCHING THE UNIT ON

Press switch On key, at the start Unit Model number & serial number will be displayed, then pressure range will be displayed

INSTRUCTIONS

- Users/customers are expected not to use the instrument below & above the pressure range mentioned, this will permanently damage the sensor
- Always Connect pressure tubes with leak free joints
- Instrument will perform "Autozero" automatically for first time at the start & a message will be displayed
- "Autozero successfully done"
- Users can also press zero key manually for 1 second to perform autozero manually
- User can change & select multiple units by pressing unit selection keys
- Upper arrow key /Increment key is used to reset the Minimum & Maximum values of pressure
- Display Back light key is used to switch Off/ On back light, it is recommended to use backlight when only needed to save battery life, backlight automatically goes "switch off" after sometime as programmed in the setting menu

PROGRAM MODE /SETTING MENU

Switch On the instrument & let it perform auto zero automatically & wait till main display starts

To enter into setting menu long press (Zero Key + Light key) together for 3 seconds continuously

The Display shows the following prompt

Password 0000

Enter password **1204** with help of shift (left) key & Up arrow /Increment key, press Zero /enter Key to enter the password

If no key is pressed for long time, the instrument will come out of program/ setting mode Press light key continuously to view back screen mode & come out of setting /program mode

FOLLOWING MENU OPTIONS ARE DISPLAYED AFTER ENTERING INTO SETTING/PROGRAM MODE

- 1. Calibration
- 2. Unit
- 3. Auto off
- 4. Battery count
- 5. Sr. No.

Press Enter key to start Calibration mode with help of enter key, After the LCD Display shows the following prompt

CALIBRATION

- 1. Step Calibration (Full calibration Mode)
- 2. Edit Values (Adjusting Calibration Values)
- 3. Sample(Changing sampling rate)
- 4. DpPoint (Deactivated)
- 5. Resolution (Increment or decrement)

STEP CALIBRATION MODE

Step Calibration Mode is full calibration Mode at 10 multiple points (at every 10 %) covering complete instrument range to provide high accuracy of 0.1 % FS throughout the operating range Use this Mode only when you have calibrated external pressure reference source & hi accuracy pressure display to calibrate this instrument

Connect the External reference pressure source with calibrated display to the instrument & following procedure.

Enter the 1. Step calibration mode with help of enter key, After the LCD Display shows the following prompt

Cali.>Step

Pressure at Zero +000.000

Adc Count

XXXX

Enter the correct Value of the pressure with help of shift left & Up arrow key

After pressure value shown in zero, Press Enter key to move next 10% point, always remember to press enter key to savethe value of pressure

Cali.>Step

Pressure at 10% +000.030 Adc Count

XXXX

After pressure value shown in 10%, Press Enter key to move next 20% point,

Follow same steps at every 10 % till step calibration is complete till SPAN , a message will appear that calibration is complete

ACTIVATION OF "EDIT VALUES "IN CALIBRATION MODE

Edit Values correction is used to perform small corrections in calibration values, specific to the calibration points or defined range

After Entering into setting Mode/Calibration

The calibration mode with help of enter key, After the LCD Display shows the following prompt

CALIBRATION

- 1. Step Calibration
- 2. Edit Values
- 3. Sample
- 4. DpPoint
- 5. Resolution

Enter the 2. Edit Values calibration mode with help of enter key, After the LCD Display shows the following prompt.

Edit Table

- 1. Pressure at Zero
- 2. Pressure at 10%
- 3. Pressure at 20%
- 4. Pressure at 30%
- 5. Pressure at 40%
- 6. Pressure at 50%
- 7. Pressure at 60%
- 8. Pressure at 70%
- 9. Pressure at 80%
- 10. Pressure at 90%
- 11. Pressure at Span

After display edit table in display inter Sr no.1 pressure at Zero with help of inter key (Zero key),

Pressure at Zero

1. Pressure : +000.000 2. Count : 208203

Edit the Pressure Value & ADC count value according to pressure value With help of left arrow (Unit) and up arrow key, after editing of count value move to edit table with help of exit key (light key).

After Show edit table in display inter Sr no.2 pressure at 10% with help of inter key (Zero key),

Pressure at 10%

1.Pressure: +000.030

2.Count: 224746

Edit the count value according to pressure value With help of left arrow(Unit) and up arrow key, after editing of count value move to edit table with help of exit key (light key).

After Show edit table in display inter Sr no.3 pressure at 20% with help of inter key (Zero key), Repeat the same procedure for other % values

Pressure at Span

1.Pressure : +000.300 2.Count : 380893

Edit the count value according to pressure value With help of left arrow(Unit) and up arrow key, after editing of count value move to edit table with help of exit key (light key).

WARRENTY CERTIFICATE

This is certify that, Dry Block Temperature Calibrator having Sr. No	
Date is propery Tested for workmanship. We Certify our Calib	rator for
satisfactory performance for the period of one year from the date of supply again	st any
manufacturing defect.	

Signature